


NOTES:

1. THE STRUCTURAL CONDITION OF THE BUILDING HAS DETERIORATED DRAMATICALLY DURING THE WINTERS OF 1992-1993 & 1993-1994. A HIGH POTENTIAL RISK OF ADDITIONAL STRUCTURAL FAILURE, DETERIORATION AND COLLAPSE EXISTS IN THE FUTURE, PARTICULARLY DURING THE WINTER.



439039

$$128 \quad 220 = 200$$

$$107 \quad 28/120 \quad 1,500 = 640$$

$$202 \quad 9,500 = 41$$

$$117 \quad 280 = 23$$

$$78 \quad 21,400$$

$$90 \quad 850 = 2,900$$

$$102 \quad 100 = 100$$

$$148 \quad 130 = 28$$

$$123 \quad 1,200/1,400 = 1,700$$

$$124 \quad 1,100 = 72$$